





30, rue Pierre-Georges LATECOERE
 05130 TALLARD – FRANCE
 Tel: +33 (0)4 92 20 16 19 Fax: +33 (0)4 92 52 69 66
 e-mail: contact@beringer-aero.com

SERVICE BULLETIN

SB-018

Revision	Date	Description	Author	Approval
0	7 Oct. 20	Initial		

	Europe	USA
Contact:	BERINGER AERO 30, rue Pierre-Georges LATECOERE 05130 TALLARD – FRANCE	BERINGER AERO USA 400 Birnie Street – Suite E Greenville, SC 29611
Technical Support:	+33 492 201 619 support@beringer-aero.com	(864)-214-4274 support@beringer-aero-usa.com

Table of Contents

1. EFFECTIVITY	2
2. BACKGROUND.....	2
3. COMPLIANCE	2
4. INSTRUCTIONS	2



30, rue Pierre-Georges LATECOERE
05130 TALLARD – FRANCE
Tel: +33 (0)4 92 20 16 19 Fax: +33 (0)4 92 52 69 66
e-mail: contact@beringer-aero.com

SERVICE BULLETIN

SB-018

1. EFFECTIVITY

This service bulletin has to be applied to ALL wheels/brakes & axles exposed to corrosive environment.

2. BACKGROUND

BERINGER AERO products may need extra protection to perform well in extreme corrosive environment.

3. COMPLIANCE

The occurrence of this maintenance can be done at any time. However, it is more efficient to do it while doing other maintenance (brake pads change, tire change...)

4. INSTRUCTIONS

Refer to maintenance working card MM-00-006 for all the instructions as well as the definition of a « corrosive environment ».