

 <p>Aeropole, 05130 TALLARD - FRANCE Tel:+33 (0)4 92 20 16 19 Fax:+33 (0)4 92 52 69 66 e-mail : contact@beringer-aero.com</p>	<h1>SERVICE BULLETIN</h1>	Manuel référence : BRG-ALTP-02
		Référence document : SB-010

This document has been produced in accordance with alternative procedure to DOA

To : All Owners/operators of the BERINGER STC-012

Subject : Update of the STC with changed hydraulic fittings.
The maintenance manual and IPC have been updated in accordance.

Type affected : All Wheel & Brake STC-012 for Extra EA-300 aircraft, all Models

Reason : With particular position and setting of the rudder pedals, the hydraulic fitting HYD-027D at the master cylinder may have an interference with the fuselage.

Delay of application : Next maintenance

Description of the modifications:

Replace the hydraulic fitting HYD-027D by the banjo fitting HYD-022VC as per the updated maintenance manual and part list :

- MM-STC-012 rev. 2
- NP-STC-012 rev.2

Date: 09.Dec.2015

Name, signature:

Rémi BERINGER

