



Aeropole, 05130 TALLARD - FRANCE  
Tel:+33 (0)4 92 20 16 19 Fax:+33 (0)4 92 52 69 66  
e-mail : contact@beringer-aero.com

# SERVICE BULLETIN

Manuel référence :  
**BRG-ALTP-02**

Référence document :

**SB-012**

This document has been produced in accordance with alternative procedure to DOA

**To :** All Owners/operators of the BERINGER STC-012

**Subject :** The STC has been updated with a new wheel P/N RA-018(A)  
The maintenance manual and IPC have been updated in accordance.

**Type affected :** All Wheel & Brake STC-012 for Extra EA-300 aircraft, all Models

**Reason :** Following SB-011 the STC has been updated with a new wheel P/N RA-018(A) in replacement of the wheel RF-005(B).

**Delay of application :** Next maintenance or within 50 FH whichever comes first

**Description of the modifications:**

Replace the wheel assembly as per the updated maintenance manual and part list :  
- MM-STC-012 rev. 3  
- NP-STC-012 rev.3

Date: 31.Jan.2017

Name, signature:

Rémi BERINGER