



30, rue Pierre-Georges LATECOERE
05130 TALLARD – FRANCE
Tel: +33 (0)4 92 20 16 19 Fax: +33 (0)4 92 52 69 66
e-mail: contact@beringer-aero.com

SERVICE BULLETIN

SB-007

Revision	Description	Date	Approval
0	Initial Revision	17 Mar 2015	
1	Update due to administrative change	26 Aug 2022	

This document has been produced in accordance with alternative procedure to DOA

To : All Owners/operators of the BERINGER STC-008

Subject : Update of maintenance intervals that have been increased to 125h instead of 100h.

Type affected : All Wheel & Brake STC-008 for DHC-6 Twin Otter

Reason : To match the Aircraft maintenance intervals

Delay of application : 12 months

Description of the modifications:

The 100h visit checks mentioned in SM-02 for aircrafts under STC-008 will be performed at 125h visit.

Name, signature:

Guillaume MASSON

END