





30, rue Pierre-Georges LATECOERE  
05130 TALLARD – FRANCE  
Tel: +33 (0)4 92 20 16 19 Fax: +33 (0)4 92 52 69 66  
e-mail: contact@beringer-aero.com

## SERVICE BULLETIN

SB-021

Revision	Description	Date	Checked	Approval
0	Initial Revision	30 March 2022	 05 Apr 2022	 05 Apr 2022

**To :** All Owners/operators of the BERINGER STC-002

**Subject :** Update of maintenance intervals that have been decreased to 3000 FH / 5 Years instead of 3500 FH / 7 Years.

**Type affected :** All Wheel & Brake STC-002 for PILATUS-PC-6

**Reason :** To match the Aircraft maintenance intervals

**Delay of application :** Immediate

### **Description of the modifications:**

Caliper pistons, rubber seals and brake fluid replacement have been modified from overhaul maintenance 3500 FH / 7 Years to 3000 FH / 5 Years.

The replacement of those parts on aircraft between 5 and 7 Years or 3000 FH and 3500 FH shall be done at the 3500 FH / 7 Years time limit, before applying STC-002 and SM-02 criteria.

Date: 31 March 2022

Name, signature:

Guillaume MASSON


END