



 30, rue Pierre-Georges LATECOERE 05130 TALLARD – FRANCE Tel: +33 (0)4 92 20 16 19 Fax: +33 (0)4 92 52 69 66 e-mail: contact@beringer-aero.com	<b>SERVICE BULLETIN</b>	<b>SB-021</b>
---	-------------------------	---------------

Revision	Description	Date	Approval
0	Initial Revision	30 March 2022	
1	Service Bulletin Reason corrected	14 Feb 2025	

**To :** All Owners/operators of the BERINGER STC-002

**Subject :** Update of maintenance intervals that have been decreased to 3000 FH / 5 Years instead of 3500 FH / 7 Years.

**Type affected :** All Wheel & Brake STC-002 for PILATUS-PC-6

**Reason :** To match the BERINGER maintenance intervals defined in the Servicing Manual [SM-01](#)

**Delay of application :** Immediate

**Description of the modifications:**

Caliper pistons, rubber seals and brake fluid replacement have been modified from overhaul maintenance 3500 FH / 7 Years to 3000 FH / 5 Years.  
The replacement of those parts on aircraft between 5 and 7 Years or 3000 FH and 3500 FH shall be done at the 3500 FH / 7 Years time limit, before applying STC-002 and SM-02 criteria.

**END**