





30, rue Pierre-Georges LATECOERE
 05130 TALLARD – FRANCE
 Tel: +33 (0)4 92 20 16 19 Fax: +33 (0)4 92 52 69 66
 e-mail: contact@beringer-aero.com

SERVICE BULLETIN

SB-022

Revision	Date	Description	Checked	Approval
0	12 Apr 2022	Initial		

	Europe	USA
Contact:	BERINGER AERO 30, rue Pierre-Georges LATECOERE 05130 TALLARD – FRANCE	BERINGER AERO USA 18 Woods Lake Road, Suite 102 Greenville, SC 29607
Technical Support:	+33 492 201 619 support@beringer-aero.com	(864)-214-4274 support@beringer-aero.us

Table of Contents

1. EFFECTIVITY	2
2. BACKGROUND.....	2
3. COMPLIANCE	2
4. INSTRUCTIONS	2

1. EFFECTIVITY

This service bulletin shall be applied to all aircrafts having regulator seepage issue.

2. BACKGROUND

BERINGER AERO regulators RE-001, RE-002 and RE-002.1 may need to be replaced in case of seepage or leakage on the venting hole. This issue does not affect flight safety as long as the leak does not create a low brake fluid level.

3. COMPLIANCE

RE-001:



venting hole

RE-002 and RE-002.1:



venting hole

4. INSTRUCTIONS

If seepage or leakage is detected on venting holes, replace RE-001, RE-002 or RE-002.1 by a new one. Contact BERINGER to get a new one.