

 <p>Aeropole, 05130 TALLARD - FRANCE Tel:+33 (0)4 92 20 16 19 Fax:+33 (0)4 92 52 69 66 e-mail : contact@beringer-aero.com</p>	<h1>SERVICE BULLETIN</h1>	<p>Manuel référence : BRG-ALTP-01</p> <p>Référence document : SB-004</p>
--	---------------------------	--

This document has been produced in accordance with alternative procedure to DOA

To : All Owners/operators of the BERINGER STC-002

Subject : Update with some changes in the maintenance manuals.
The O-ring seal J-JTR-010N can be replaced by another O-ring seal: JNT-007N

Type affected : All Wheel & Brake STC-002 for Pilatus PC-6

Reason : Modification of the maintenance manuals

Delay of application : 12 months

Description of the modifications:

The next documents have been updated with minor changes that do not affect the original design.

MC-STC-002 rev. 2
MM-STC-002 rev. 2
NP-STC-002 rev. 1

Date: 10.Oct.2012

Name, signature:

Rémi BERINGER

