



Aeropole, 05130 TALLARD - FRANCE
Tel:+33 (0)4 92 20 16 19 Fax:+33 (0)4 92 52 69 66
e-mail : contact@beringer-aero.com

SERVICE BULLETIN

Manuel référence :
BRG-ALTP-02

Référence document :

SB-007

This document has been produced in accordance with alternative procedure to DOA

To : All Owners/operators of the BERINGER STC-008

Subject : Update of maintenance intervals that have been increased to 125h instead of 100h.
The manuals have been updated in accordance.

Type affected : All Wheel & Brake STC-008 for DHC-6 Twin Otter

Reason : To match the Aircraft maintenance intervals

Delay of application : 12 months

Description of the modifications:

The next documents have been updated to:
- MM-STC-008 rev. 2

Date: 17.March.2015

Name, signature:

Rémi BERINGER