

 <p>Aeropole, 05130 TALLARD - FRANCE Tel:+33 (0)4 92 20 16 19 Fax:+33 (0)4 92 52 69 66 e-mail : contact@beringer-aero.com</p>	<h1>SERVICE BULLETIN</h1>	Manuel référence : BRG-ALTP-02
		Référence document : SB-009

This document has been produced in accordance with alternative procedure to DOA

To : All Owners/operators of the BERINGER STC-012

Subject : Update of the STC with the use of longer bolts and axle.
The maintenance manual and IPC have been updated in accordance.

Type affected : All Wheel & Brake STC-012 for Extra EA-300 aircraft, all Models

Reason : For special use or long taxi operation the thicker disc is an alternative to the standard disc.

Delay of application : 6 months

Description of the modifications:

The next documents have been updated to:

- MM-STC-012 rev. 1
- NP-STC-012 rev.1

Date: 22.Oct.2015

Name, signature:

Rémi BERINGER

