



Aeropole, 05130 TALLARD - FRANCE
Tel:+33 (0)4 92 20 16 19 Fax:+33 (0)4 92 52 69 66
e-mail : contact@beringer-aero.com

SERVICE BULLETIN

Manuel référence :
BRG-ALTP-02

Référence document :

SB-013

This document has been produced in accordance with alternative procedure to DOA

To : All Owners/operators of the BERINGER STC-002

Subject : Update of the STC with optional brake pads PQT-016 with higher operating temperature.
The manuals and IPC have been updated in accordance.

Type affected : All Wheel & Brake STC-002 for Pilatus PC-6

Reason : For high temperature and intensive use or long taxi operation the PQT-016 brake pads is an alternative to the standard PQT-008 brake pads.

Delay of application : NA

Description of the modifications:

The next documents have been updated to:

- MC-STC-002 rev. 6
- MM-STC-002 rev. 6
- NP-STC-002 rev.5

STC change approved by EASA 10029629 rev.4 on the 13th of April 2017

Date: 31.May.2017

Name, signature:

Frédéric SALLÉ