





Aeropole, 05130 TALLARD  
Tel: +33 (0)4 92 20 16 19 Fax: +33 (0)4 92 52 69 66  
e-mail : contact@beringer-aero.com

## NOMENCLATURE PIECES

Manuel référence :  
**BRG-ALTP-02**

Référence document :  
**NP-STC-011**

			Signature du responsable conception
<b>STC-011 BERINGER kit for LAK17A</b>			
Révisions	Date	Sujet	
00	12/01/2015	Initial edition	
01	03/07/2017	Update with new wheel P/N	
02	19 Oct 2021	Addition of the SensAIR system in option and removal of the tire.	



Aeropole, 05130 TALLARD  
Tel: +33 (0)4 92 20 16 19 Fax: +33 (0)4 92 52 69 66  
e-mail : contact@beringer-aero.com

## NOMENCLATURE PIECES

Manuel référence :  
**BRG-ALTP-02**

Référence document :  
**NP-STC-011**

Part number	Description	Qty. per Kit
RF-019	Wheel 5.00-5	1
EA-006E	Brake Assembly	1
AV-LAK-002*	Caliper plate	1
V-FHC-008	Caliper fixing screws FHC M6-16	3
AV-HPH-003	Wheel axle	1
AV-LAK-003	Bearing spacer	1
ZPA02	Safety wire 1mm	1
MM-001E	Master cylinder	1
LM-003E	Pressure limiter 35bars	1
HYD-032	Brake line	3m
HYD-002OP	Banjo 20°	4
HYD-003P	Banjo screw	2
HYD-005B	Copper seal	10
HYD-046P	Banjo screw dual	1
AV-PLASCLAMP	Plastic clamp	10
<b>TP-005</b>	<b>SensAIR for 5" wheel</b>	<b>(Option)</b>

\*Caliper plate AV-LAK-002 can be replaced by AV-LAK-001 (centre line 59mm)