



Aeropole, 05130 TALLARD  
Tel: +33 (0)4 92 20 16 19 Fax: +33 (0)4 92 52 69 66  
e-mail : contact@beringer-aero.com

## NOMENCLATURE PIECES

Manuel référence :  
**BRG-ALTP-02**

Référence document :  
**NP-STC-013**

			Signature du responsable conception
<b>BERINGER STC-013 for DA42</b>			
Révisions	Date	Sujet	
0	28.05.2015	Emission initiale	
1	19.02.2017	Update with new wheel	
2	10.12.2021	Addition of Sensair Option	<b>BERTELOOT CELIA</b> 



Aeropole, 05130 TALLARD  
Tel:+33 (0)4 92 20 16 19 Fax:+33 (0)4 92 52 69 66  
e-mail : contact@beringer-aero.com

## NOMENCLATURE PIECES

Manuel référence :  
**BRG-ALTP-02**

Référence document :

**NP-STC-013**

Part number	Description	Qty. DA 42	Qty. DA 42 NG
RF-006(A)	Main wheel assembly	2	2
EA-003.7N(A)	Brake assembly	2	2
AV-DIAM-401(A)	Main wheel axle	2	2
AV-DIAM-402(B)	Axle plate	2	2
AV-DIAM-403(A)	Axle washer	2	2
BGE-021(A)	Bushing	4	4
VIS-011(A)	Screw	4	-
VIS-013(A)	Screw	4	-
VIS-012(A)	Screw	-	4
VIS-014(A)	Screw	-	4
ECR-001(C)	Axle nut	2	2
BCH-004(B)	Wheel cap	2	2
J-JTR-020N	O-Ring	2	2
RA-014(A)	Nose wheel assembly	1	1
AV-DIAM-404(A)	Nose wheel axle	1	1
AV-DIAM-405(B)	Axle End	2	2
AV-DIAM-406(A)	Spacer	2	2
VIS-009(A)	Screw	1	1
E-HN-004	Nut	1	1
MP-003.3N(A)	Master cylinder	4	4
RV-003N(A)	Reservoir	2	2
AV-DIAM-407(A)	Brake line	2	2
HYD-003P	Banjo bolt	10	10
HYD-005B	Copper seal	30	30
HYD-019VC	Banjo straight	2	2
HYD-006	Adaptor	4	4
HYD-027D	90° Elbow	4	4
ETQ-007(A)	MIL-PRF-87257 sticker	2	2
ZPA02	Safety wire	2	2
TP-005	SensAIR on 5" wheel	Option	Option
TP-006	SensAIR on 6" wheel	Option	Option