

 <p>Aeropole, 05130 TALLARD - FRANCE Tel:+33 (0)4 92 20 16 19 Fax:+33 (0)4 92 52 69 66 e-mail : contact@beringer-aero.com</p>	<h1>SERVICE BULLETIN</h1>	Manuel référence : BRG-ALTP-02
		Référence document : SB-006

This document has been produced in accordance with alternative procedure to DOA

To : All Owners/operators of the BERINGER STC-002

Subject : Update of the STC with an optional small wheel size 24x7.7 and a special tail wheel axle to install the rear ski.
The maintenance intervals of the brake unit have been increased to 3500h and 7 years.
The manuals have been updated in accordance.

Type affected : All Wheel & Brake STC-002 for Pilatus PC-6

Reason : For skis installation, the small wheels replace the larger wheels.

Delay of application : 12 months

Description of the modifications:

The next documents have been updated to:

- MC-STC-002 rev. 4
- MM-STC-002 rev. 4
- NP-STC-002 rev.3

Date: 02.March.2015

Name, signature:

Rémi BERINGER

