

 <p>Aeropole, 05130 TALLARD - FRANCE Tel:+33 (0)4 92 20 16 19 Fax:+33 (0)4 92 52 69 66 e-mail : contact@beringer-aero.com</p>	<h1>SERVICE BULLETIN</h1>	<p>Manuel référence : <b>BRG-ALTP-02</b></p> <hr/> <p>Référence document : <b>SB-008</b></p>
--	---------------------------	--

This document has been produced in accordance with alternative procedure to DOA

**To :** All Owners/operators of the BERINGER STC-002

**Subject :** Update of the STC with an optional thicker disc P/N DSC-011.2(A) with higher energy capacity.  
The manuals and IPC have been updated in accordance.

**Type affected :** All Wheel & Brake STC-002 for Pilatus PC-6

**Reason :** For special use or long taxi operation the thicker disc is an alternative to the standard disc.

**Delay of application :** NA

**Description of the modifications:**

The next documents have been updated to:

- MC-STC-002 rev. 5
- MM-STC-002 rev. 5
- NP-STC-002 rev.4

STC change approved by EASA 10029629 rev.3 on the 22<sup>nd</sup> of September 2015

Date: 24.Nov.2016

Name, signature:

Rémi BERINGER

